

PALERMO CULVERT INVENTORY - 1990

TABLE PF-5

POLE #	SIZE	CONDITION	COMMENTS
Road: Bushey Rd. Total Culverts: 2 # Need Replacing: 0			
36	12" x 33'	Good	
36-5	12" x 30'	Good	
Road: Cane Hill Rd. Total Culverts: 4 # Need Replacing: 0			
2	18" x 40'	Good	
2	12" x 30'	Good	
3	26" x 64'	Good	
3	16" x 24'	Good	
Road: Greeley Corner School or Sidney Jones Rd. Total Culverts: 2 # Need Replacing: 0			
33-2	12" x 30'	Good	
56-2	18" x 18'	Fair	
Road: Jones Rd to Turner Ridge Rd. Total Culverts: 11 # Need Replacing: 2			
7	36" x 36'	Good	
7	18" x 40'	Good	
12	10" x 36'	Good	
14	15" x 36'	Good	
27	12" x 32'	New	
28	12" x 40'	New	
32-91	15" x 30'	Fair	Robert Potter's
	15" x 24'	New	
	15" x 24'	No Good	
	24" x 24'	No Good	
	36" x 32'	Good	Marty Hulzers Wood Lot
Road: Somersville to Brown Town Rd, China. Total Culverts: 3 # Need Replacing: 2			
	16" x 24'	Replace Now	
49	12" x 33'	Replace	
56	24" x 38'	Fair	

POLE #	SIZE	CONDITION	COMMENTS
Road: Level Hill Rd. Total Culverts: 64 # Need Replacing: 0			
1	18" x 3'	Fair	Begin at Richard Dyer
2 & 3	24" x 30'	Good	Begin at Richard Dyer
5 & 6	16" x 34'	Good	Begin at Richard Dyer
8 & 9	16" x 33'	Good	Begin at Richard Dyer
8 & 9	16" x 27'	Fair	Begin at Blairs
8 & 9	18" x 56'	Good	
12	12" x 15'	Fair/Plugged	Smith Cemetery/North End
14	18" x 69'	Good	Smith Cemetery/South End
18s	16" x 39'	Good	Gordon Swift
20s	15" x 24'	Good	Frank Lee
20	15" x 24'	Good	Bill Haskell
20 & 21	15" x 33'	Good	
23-28	24" x 78'	Fair	
24	15" x 33'	Good	
25	15" x 33'	Good	
27	15" x 33'	Good	Jim Rd
01	18" x 57'	Good	
02	18" x 57'	Good	
02 & 03	18" x 33'	No Good	
03	15" x 24'	Good	Reinforce Cement Pipe
12	18" x 42'	Fair	
13	15" x 30'	Good	
015	18" x 33'	Good	
017	6" x 100'	Good	Under Road Drainage Pipe
018	36" x 100'	Fair	
019	15" x 30'	Good	
Richard Sand Knoll	24" x 66'	Good	

POLE #	SIZE	CONDITION	COMMENTS
Road: Level Hill Rd (cont) Total Culverts: 64 # Need Replacing: 0			
Turner Sand Knoll	15" x 27'	Good	
Prop. Sand Knoll	15" x 24'	Good	
In Woods	18" x 39 1/2'	Good	
By Spring	18" x 42'	Good	
Bowler Woods	15" x 39'	Good	End Damaged
Bowler Pond	15" x 36'	Fair	
Swimming Hole	15" x 36'	Fair	
Bowler Pond	15" x 36'	Good	
5	12" x 24'	Fair	Templeton & Greenwood
3-5	12" x 24'	Good	Templeton & Greenwood
2	30" x 45'	Good	Bowler Pond Outlet
34	18" x 42'	Fair	
42	15" x 30'	Good	
42	No culvert but needs one		Kelton Gliden
43	12" x 30'	Good	
45	15" x 30'	Good	
45	18" x 51'	Good	
45	15" x 30'	Good	
33	18" x 54'	Good	
30	15" x 27'	Good	
30	15" x 24'	Good	
30	15" x 30'	Good	
26-57s	18" x 33'	Good	
26-57	18" x 40'	Good	

POLE #	SIZE	CONDITION	COMMENTS
Road: Level Hill Rd (cont) Total Culverts: 64 # Need Replacing: 0			
24-24	18" x 40'	Good	
23	18" x 30'	Good	
22	15" x 30'	Good	
22	24" x 30'	Good	
22	15" x 30'	Good	
21	15" x 33'	Good	
20	24" x 68'	Good	
20-19	15" x 32'	Good	
10 1/2-11	18" x 51'	Good	Plugged
9	15" x 30'	Good	
8	15" x 40'	Good	
6 1/2	15" x 32'	Good	
5	36" x 60'	Good	
2	18" x 60'	Good	
Road: Harry Moss Rd or Lucarelli Rd Total Culverts: 1 # Need Replacing: 0			
0201	12" x 27'	Fair	Needs 2' extension, plugged
Road: Old Rt. 3 from Sawdust to Rt. 3 West Total Culverts: 3 # Need Replacing: 5			
177	24" x 50'	Fair	
99	12" x 32;	Good	
173	12" x 32'	Good	
Road: Hostile Valley & Chisolm Pond Rd Total Culverts: 40 # Need Replacing: 5			
Dale Mckenney	18"	No Good	
Potash Hill		Plugged	Stone Culvert
11 & 12		Fair	
11-12/17		Good	End Bent
11-18	2'	Fair	Two side by side

TABLE PF-5 PALERMO CULVERT INVENTORY - 1990 (cont.)

POLE #	SIZE	CONDITION	COMMENTS
Road: Hostile Valley & Chisolm Pond Rd (cont) Total Culverts: 40 # Need Replacing: 5			
Frank Brown Brook	1-3'	Good	
	1-2'	New	
	1-2'	Good	
26	18"	Replace	End Damaged Dale McGee
31	2'	Fair	
37/24	2'	Fair	
Chisolm Pond Road	3'	Good	
85/28	1-5'-12'	Good	By McKenney Camp
82/31 & 82/30	2'	Good	Jerry Pollards
72/41	2'	Fair	Ft of Hill below Carr Pl
72/63		Fair	By Vaughn Cails Place
72/-		Fair	By Vaughn Cails Place
-	16"	No good	
-	16"	No good	On flat
57/49		Plugged	Sargent Pl & Harold Stiefen
	16"	Fair	Below Donney Glidden Place
38	16"	Fair	
	12"	Fair	Aggy Place
	1-6'-2-3'	Good	Brook by Mullens
Sand Hill Cemetery Rd	7'	Good	Steam Boiler for Sand Hill Cemetery Rd
		Replace now	Robisons new house
		Reset End Bent	Robisons new house
	Needs a culvert		Robisons Camp Rd
	12"	Good	Robisons Camp Road curve
		Fair	By Keith Higgins pasture

POLE #	SIZE	CONDITION	COMMENTS
Road: Hostile Valley & Chisolm Pond Rd (cont) Total Culverts: 40 # Need Replacing: 5			
		No good	By Keith Higgins house
		Good	By Harold Sennets
		Plugged	By Harold Sennets blueberries
	18"	Fair	By Harold Sennets
	18"	Fair	By Harold Sennets
		Egg shaped	
Road: Plummer Rd Total Culverts: 9 # Need Replacing: 3			
502	2'	Fair	
505	16" - 24'	No Good	
506	18"	Fair	Plugged
508 & 509	4'6"	Good	
-	2'	No Good	Below Redmans Camp
-	18"	Good	
-	2'	Good	
Road: S Liberty Rd from Rt 3 to S Liberty line Total Culverts: 17 # Need Replacing: 4			
-	18" x 40'	No Good	Half plugged
10 & 9	18"	Fair	Needs to be cleaned out
	16"	Fair	Priest House (Mildred)
	16"	Good	Mack Donalds
	2' x 38"	Replace	Hannon Kerwins
	14"	Good	Colby Brook multiplat culvert
	18"	Good	
	8 Drive culverts		Two need to be replaced
101	18"	Fair	
101	16"	Good	

TABLE PF-5 PALERMO CULVERT INVENTORY - 1990 (cont.)

POLE #	SIZE	CONDITION	COMMENTS
Road: S. Liberty Rd. to Banton Rd. Total Culverts: 29 # Need Replacing: 4			
Fire Rd 12	2' x 57'	Good	
12	1' x 40'	Good	
18/19	16"	Fair	Plugged
22/23	May be a culvert. If not, needs one.		
24/39/25	18"	Fair	
	8'	Good	Multiplate
	2'	New	Colby Brook & Banton's Mill
35	2'	Good	
36/37	3'	Good	
42/43	2' x 34'	Replace	
	6" pipe	OK	Dwayne McKenny
	12"	New	
2 Hydra	12"	Good	Leo Smith
40-41		Good	Repair
54	5'	Plugged	Gale Gigure
39/55	16"	Good	Roaring Brook
56	16"	?	Plugged
57	16"	Good	
63	16"	Plugged	Needs 2' extension
64	15"	Fair	Stevensons. Clean end.
71	15"	Fair	Needs cleaning
-	3'	Good	Bryant Place
-	15"	Replace	Plugged
Road: Lenfest Cemetery or Mountain Rd. Total Culverts: # Need Replacing: 1			
47	16"	Replace	
11/92	12"	Fair	Plugged
	16"	Plugged	Clean now

POLE #	SIZE	CONDITION	COMMENTS
Road: Lenfest Cemetery or Mountain Rd. Total Culverts: 6 # Need Replacing: 1			
By Hatchery		Both ends plugged	Clean now
	16" x 1/2"	Pipe good	Water main
Turner Ridge Road	16" x 1/2"	Good	
Road: Lincoln County Total Culverts: # Need Replacing:			
Palermo plows & maintains for county and is reimbursed by county.			
	2' & 3'	Fair	
		Fair	Bog Bridge
Road: Gore Rd. or Hatchery Rd. Total Culverts: # Need Replacing:			
16/97	15"	Replace	Carlsons
15-14/95	Size and Condition ?		Plugged
Hatchery Hill	2'	Fair	Needs cleaning, one end
11/92	14"	Clean ends	Nora Armstrong
	16"	Good	By Hatchery
			Bridge over Sheepscot River by Fish Hatchery
-	2-16" pipe		Water main
-	1-16" pipe		Water main
Road: Parmenter Rd. Total Culverts: 16 # Need Replacing: 3			
32	12" x 18'	Good	
33	12" x 18'	Good	
9	9" x 36'	New	Plastic
12-12	12" x 33'	Good	
Box 240	12" x 33'	Replace	
15, 31, 15	18" x 33'	Good	
Sucker Brook	36" x 28'	New	
	24" x 28'	Replace	

PALERMO CULVERT INVENTORY - 1990 (cont.)

TABLE PF-5

POLE #	SIZE	CONDITION	COMMENTS
Road: Parmenter Rd (cont) Total Culverts: 16 # Need Replacing: 3			
	18" x 28'	Fair	
	10" x 28'	Fair	
	10" x 20'	Fair	
	16" x 26'	Good	Needs repair patch
Hanson Place	16" x 21'	Good	Clairs Farm Dr
	15" x 24'	Fair	
	18" x 22'	Replace	
4 Corners	15" x 18'	Good	
4 Corners	20" x 21'	Fair	
Road: Marden Hill Total Culverts: 11 # Need Replacing: 2 1?			
701, 21, 141	16" x 21'	Replace	
	16" x 21'	Fair	
42 Burgess	12" x 21'	New	
42 Burgess	16" x 18'	?	Plugged
	24" x 18'	Fair	Jean Rowe Place
	12" x 20'	Replace	Jean Rowe Place
	18" x 30'	Fair	Garry Dyer
	48" x 35'	Good	Bottom of Marden Hill
	16" x 32'	Good	Bottom of Marden Hill
	12" x 33'	Good/Plugged	Beverly Hasel
504	15" x 33'	Good	
Road: Nelson Lane Total Culverts: 7 # Need Replacing: 1			
13-13	15" x 28'	Fair	
11-11	15" x 34'	Fair	
8-8	16" x 42'	Replace	
7-7	15" x 28'	Fair	
6-6	18" x 33'	New	

POLE #	SIZE	CONDITION	COMMENTS
Road: Nelson Lane (cont) Total Culverts: 7 # Need Replacing: 1			
2-2	26" x 36'	Fair	
Road: Joe Martin Rd Total Culverts: 11 # Need Replacing: 2			
Bridge by Hatchery built by State			
3 & 4	-	New	Dusty's upper dr
3 & 4	-	Fair	
	12" x 30'	Replace	Dusty's lower dr.
	-	Good	Bottom of J.H. Hill
On flat	24" x 21'	Good	Needs more gravel over top
On flat	18" x -	Good	End damaged
On flat	18" x -	Fair	
On flat	18" x -	No good	
On flat	3' x -	Fair	
By Cathy Haskell's	-	Good	
544/80	12" x 18'	Fair	Jerry Fuller's Drive (old culvert, new drive) 8-90
Road: Belden Woods Total Culverts: 9 # Need Replacing: 1			
15-21-15	15" x 21'	Good	
17	15" x 27'	Fair/Repair	Culvert pulled apart about 1 ft in middle of road
18	12" x 24'	Good	
19	14" x 24'	Good	One end plugged
23			One stone culvert should be replaced
25	16" x 18'	Good	Reset
28	- x 18'	Clean out	May be stone culvert
32	48" x 42'	Good	
	16" x 21'	Good	
Road: Ralph Sabin Rd Total Culverts: 2 # Need Replacing: 0			
21	18" x 33'	Fair	
22	12" x 18'	Good	

POLE #	SIZE	CONDITION	COMMENTS
Road: Rowe Rd. Total Culverts: 12 # Need Replacing: 3			
		Fair	Culvert Flossey's Mailbox
		Fair	Folssey's driveway culvert
		No good	Flossey's Chickenhouse
507		Good	
509/510		New/2 yrs.	Between poles
		No good	Rowe Place
		New	
17		Relocate	Garish place
15		Plugged up	
9	4'	Fair	Arnold Lane Turn
		Fair	Diann Parsons
		Fair	Cindy Pottle
Road: Weston Ridge Rd from Albion Line to China line Total Culverts: 22 # Need Replacing: 1			
029	-	Good	Clean ends
033 & 034	16" x 33'	Good	
035	18" x - Rock drain	?	
038	-	Fair	Reset
037	15" x 21'	Fair	Raymond Carey Dr
027 & 028	15" x 12'	?	Toney Tuttle, clean ends
1	2' x -	Fair	
2	16" x -	Good	
3	16" x -	Good	
8	- x -	New	
10	- x -	Fair	
17	- x -	New	
23 (Two drive cu)	15" x 18' 15" x 21'	Fair	
23	15" x 20'	Fair	
24	15" x 18'	Fair	Coney Haskell

POLE #	SIZE	CONDITION	COMMENTS
Road: Weston Ridge Rd from Albion Line to China line (Cont) Total Culverts: 22 # Need Replacing: 1			
28/16-2	- x -	New	Haskell's Turn & Mann Rd
26-01	12" x 20'	New	
7	- x -	New	
11	- x -	New	
23	- x -	Replace before paving	